

Trestle Bridge Presentation – October 11, 2022



Franklin
NEW HAMPSHIRE
The Three Rivers City



McFarland Johnson

Introduction

- Seth Creighton, AICP – Planning & Zoning Director
City Project Manager
- Brian Colburn, PE – MJ Project Manager
- Ron Joy, PE – MJ Structural Engineer
- Chris Gagne – MJ Structural Engineer



Agenda

- Project Description
- Summary of Inspection Findings
- Review of Conceptual Alternatives
- Cost Estimates
- Public Feedback / Questions
- Discussion on Next Steps



Project Description

- Construct a Pedestrian Connection Between Winnepesaukee River Trail and Mill City Park
- Awarded a Grant from NHDOT in 2019
 - NHDOT Funding \$512,000
 - City Funding \$128,000
 - Total Funding \$640,000
 - (Assumed Replacing Railroad Ties with Solid Timber Deck)
 - Project Must Follow Prescribed Design Process



Design Process

- Engineering Study
 - Bridge Inspection
 - Develop Alternatives
 - Public Input
 - Select Locally Preferred Alternative
- Preliminary Design
- Final Design
- Construction



September 1967



Franklin
NEW HAMPSHIRE
The Three Rivers City



McFarland Johnson

History of Franklin Tilton Railroad

- 5-mile Franklin-Tilton RR Spur Between Winnepesaukee Rail Division and B&M Northern Line
- 1889 Franklin-Tilton RR Charter
- 1891 First Sulphite RR Bridge
- 1895 B&M RR Leases Railroad Line
- 1896 Present Sulphite RR Bridge
- Trestle Bridge Built
- 1890s International Paper Buys Mill
- 1920s Paper Mill Closes
- 1936 Rail Service Stopped
- 1940 Request to ICC to Abandon
- 1973 Line Decommissioned




Description of Bridge

- 15-Spans, 356' long, 12' wide, 20' above ground
- 3 types of trestle spans
 1. Standard (Spans 1-6 & 15)
 2. A-Frame (Spans 8-13)
 3. Inverted King Post (Spans 7 & 14)




1. Standard Span

- 
- A photograph of a wooden trestle bridge spanning a river. The bridge is constructed from numerous vertical wooden posts (piers) supporting a series of horizontal wooden beams (trusses). The background is filled with lush green trees and foliage, suggesting a rural or natural setting. The image is slightly faded, serving as a background for the text overlay.
- Standard for Branch Lines
 - Height under 12 feet
 - Height between 12-19 feet
 - Height over 19 feet
 - Maximum 14 foot span
 - Consists of series of nearly identical vertical supports holding up a succession of short spans.
 - Direct load path from top of rail to foundation



2. A-Frame Span

- For span lengths greater than standard trestle span, A-frames effectively provide additional stringer support.
- Additional longitudinal bracing of adjacent spans are required to aid the bridge in resisting horizontal forces acting through the frame members.



3. *Inverted King Post Span*

- Inverted King Post provides additional stringer support.
- Incorporate a short section of a standard timber bent (with a cap and sill).
- Stringers function as truss members with combined axial compression (truss action) and flexural (floor system bending) stresses.
- Most distinguishable element on the bridge.



Resistance Microdrilling for Timber Inspection




- Highly calibrated drill used to identify timber condition
- Measures forward pressure and torsional resistance needed to advance a 1/16" diameter drill bit into material
- Plots Resistances vs. Depth in real time on built in display
- DOES NOT measure strength of wood – only verifies condition relative to resistances throughout cross-section



Resistance Microdrilling for Timber Inspection

SAMPLE DRILL RESULTS

- Note the drilled dimension is 11.75" in all members
- Top Left – Quality wood, no obvious signs of defects
- Bottom Left – Majority is OK, but middle 1.5" is rotted
- Bottom Right – The exterior 1" on each side is ok, but rest of section is deteriorated



Track View



2008

2020

2022



Franklin
NEW HAMPSHIRE
The Three Rivers City



McFarland Johnson

Condition Summary Table - Bents

	Cap	Post 1	Post 2	Post 3	Post 4	Comments
Bent 1		DB, SD	DB, DM	DM	RE, SD, DB (6')	
Bent 2	RE	RE, DB	RE, DM	DM	RE, DB	All columns have discrete rot, but generally okay.
Bent 3	RE, HO	RE, DM, HO	RE, DT, HO	RE, DT, HO	RE, DB	Top half of C4 may be able to be salvaged.
Bent 4	CR	RE		RE, DB	RE, DB	
Bent 5	RE, ST	DB	RE, DT	DB	RE, ST	
Bent 6		RE	RE, DB, DT			
Bent 7	R	RE, DT, DB	RE, DT, SD	RE, DB, DM	ST, SD, DB, DT	Pipe rolled onto/resting on C4.
River Bent 8	R, CR	RE, DB (6')	RE, R, SD	DB	RE, DB (5')	
River Bent 9	CR	DT, DM	R, SD	DB, SD	DB, SD	Could not access bottom. Visual rot at base of all 4 columns - severity unknown.
River Bent 10	ST	DM, HO	DB	RE, DM	DM, SD	Could not access bottom. Cap showing signs of shear distress.
River Bent 11	ST, SD	RE, ST	DB (3'), DT	RE, DB, HO, SD	RE	Cap rotting at ends, solid under bearing area.
River Bent 12	RE	RE, ST, DB (3')	RE, DB, DM, HO, SD	RE, DM, SD	RE, SD	Visual inspection only at bent cap (top).
Bent 13	CR	RE, HO, DT (6')	RE, HO, DT (6')	RE, HO, DT (6')	RE, HO, DT (3')	Bolsters are crushed.
Bent 14	CR	RE, DB	RE, DB	RE, DB, SD	RE, DB	Bolsters are crushed. C2 and C3 are doubled/twin columns (each).

Timber Defects	
CR	Crushed
ST	Split
DB(feet)	Deteriorated Bottom (feet)
DM (feet)	Deteriorated Mid-Height (feet)
DT(feet)	Deteriorated Top (feet)
HO	Hollow
R	Rot
RE	Repaired (Previously)
SD	Surface Deterioration
	Retain Member
	Replace Member
	Repair Member Option



Condition Summary Table - Stringers

	Stringer 1	Stringer 2	Stringer 3	Stringer 4	Stringer 5	Stringer 6
Span 1	DT					HO
Span 2	HO	HO, R		ST		
Span 3	DT, ST			DT, R		
Span 4	HO, R	R		DT		DT
Span 5		DT	DT	DT	DT	DT
Span 6	R	DT, R	DT, R	DT, R	DT, R	DT, R
Span 7	R @ B7		R @ B7			
Span 8	R @ B7	R @ B7	R @ B7	R @ B7	R @ B7	R @ B7
Span 9		R			DT, HO, R	DT, HO, R
Span 10					R	
Span 11					R	
Span 12		R			DT, R	R
Span 13			R	R	R	
Span 14		R			R	
Span 15						

Timber Defects	
CR	Crushed
ST	Split
DB(feet)	Deteriorated Bottom (feet)
DT(feet)	Deteriorated Top (feet)
R	Rot
HO	Hollow
RE	Repaired (Previously)
SD	Surface Deterioration
FL	Full Length
	Retain Member
	Replace Member
	Repair Member

*Note that surface deterioration is typical for tops of all stringers in all spans

**Note that this table is based on hands on inspection from under the structure. Top side inspection was partially visual due to restricted access.



Condition Summary Table – A-Frames & Truss

	A-Frame Cap	A-Frame Diagonals				King Post
		U. Stream, B. Bent	D. Stream, B. Bent	U. Stream, F. Bent	D. Stream, F. Bent	
Span 1	N/A	N/A	N/A	N/A	N/A	N/A
Span 2	N/A	N/A	N/A	N/A	N/A	N/A
Span 3	N/A	N/A	N/A	N/A	N/A	N/A
Span 4	N/A	N/A	N/A	N/A	N/A	N/A
Span 5	N/A	N/A	N/A	N/A	N/A	N/A
Span 6	N/A	N/A	N/A	N/A	N/A	N/A
Span 7	N/A	N/A	N/A	N/A	N/A	HO, R
Span 8	R		R	ST	R	N/A
Span 9						N/A
Span 10						N/A
Span 11			R			N/A
Span 12	R	R	R			N/A
Span 13	ST	R		HO, ST		N/A
Span 14	N/A	N/A	N/A	N/A	N/A	CR
Span 15	N/A	N/A	N/A	N/A	N/A	N/A

Timber Defects	
CR	Crushed
ST	Split
DB(feet)	Deteriorated Bottom (feet)
DT(feet)	Deteriorated Top (feet)
R	Rot
HO	Hollow
RE	Repaired (Previously)
SD	Surface Deterioration
FL	Full Length
	Retain Member
	Replace Member
	Repair Member



Condition Summary Table

Element	Total	Green (Retain)	%	Red (Replace)	%	Yellow (Repair)	%
Bents	70	27	39%	20	29%	23	33%
Stringers	90	10	11%	38	42%	42	47%
A-Frames	30	12	40%	8	27%	10	33%
	190	49	26%	66	35%	75	39%



Bent Condition



BENT 1



BENT 1



BENT 3



Bent Condition



BENT 3



BENT 3



BENT 4



Bent Condition



BENT 7



BENT 7



BENT 7



Bent Condition



BENT 10



BENT 11



BENT 13



Bent Condition



BENT 13

BENT 13



SPAN 13



River Piers Condition



Franklin
NEW HAMPSHIRE
The Three Rivers City



McFarland Johnson

River Piers Condition



Franklin
NEW HAMPSHIRE
The Three Rivers City



McFarland Johnson

River Piers Condition



Franklin
NEW HAMPSHIRE
The Three Rivers City



McFarland Johnson

River Piers Condition



Structural Inspection Findings

- Portions of the Truss are in Poor Condition
- Truss is Continuing to Deteriorate
- 2019 Inspection Led to Path Relocation



Current Alternatives

- Rehabilitate Existing Railroad Trestle
 - Remove Rail, Ties, & Stringer and Put on New Deck & Historic Style Railing
 - Rehabilitate and Replace Trestle Members
- New Railroad Trestle
 - Replicate Existing Design
 - All New Timber Members
- New Pedestrian Bridge Upstream



Alternative Cost Estimates

	ALTERNATIVE COST ESTIMATES			
	FULL HISTORIC RESTORATION ALTERNATIVES FOR PEDESTRIAN LOADING		NEW PEDESTRIAN BRIDGE & STABILIZE TRESTLE	NO-BUILD & STABILIZE TRESTLE
	REHABILITATE TRESTLE	REPLACE TRESTLE IN- KIND		
TIMBER TRESTLE WORK	\$ 2,200,000	\$ 1,925,000	\$ 1,000,000	\$ 1,000,000
NEW CONCRETE RIVER PIERS (TBD)	\$ 550,000	\$ 550,000	\$ -	\$ -
PEDESTRIAN DECK & WROUGHT IRON HISTORIC STYLE RAILING	\$ 625,000	\$ 625,000	\$ -	\$ -
CONTINGENCY	\$ 350,000	\$ 300,000	\$ 225,000	\$ 225,000
MOBILIZATION	\$ 350,000	\$ 300,000	\$ 225,000	\$ 225,000
NEW PEDESTRIAN BRIDGE & FOUNDATIONS	\$ -	\$ -	\$ 1,495,000	\$ -
APPROACH WORK	\$ 75,000	\$ 75,000	\$ 60,000	\$ -
TOTAL CONSTRUCTION ESTIMATE	\$ 4,150,000	\$ 3,775,000	\$ 3,005,000	\$ 1,450,000
DESIGN ENGINEERING, GEOTECHNICAL, & PERMITTING	\$ 375,000	\$ 350,000	\$ 240,000	\$ 150,000
CONSTRUCTION ENGINEERING (7% CONSTRUCTION)	\$ 290,000	\$ 260,000	\$ 210,000	\$ 100,000
TOTAL PROJECT ESTIMATE	\$ 4,815,000	\$ 4,385,000	\$ 3,455,000	\$ 1,700,000
CITY SHARE	20%	20%	20%	100%
CITY COST	\$ 963,000	\$ 877,000	\$ 691,000	\$ 1,700,000

\$550,000 Already Funded (\$440,000 DOT - \$110,000 City)



New Railroad Trestle Alternatives

- Modern Materials Could Be Used to Build a More Efficient Trestle
 - Fewer Bents
 - Longer Spans
 - Would Change the Look of the Trestle
 - Would Lower Construction Costs
 - Require Additional Coordination with Resource Agencies
 - Wide Range of Options



Questions



Franklin
NEW HAMPSHIRE
The Three Rivers City



McFarland Johnson

Next Steps

- Select Locally Preferred Alternative
- Review with NHDOT
- Identify Additional Funding Sources
- Continue with Design Development



Contact Information

Seth Creighton, AICP

City Planning & Zoning Director

screighton@franklinnh.org

603-934-2341

Brian Colburn, PE

McFarland Johnson Project Manager

bcolburn@mjinc.com

603-225-2978



Franklin
NEW HAMPSHIRE
The Three Rivers City



McFarland Johnson